



Photo 1 – Accident Site – Courtesy of FAA



Photo 2 – Main Wreckage – Courtesy of FAA



Photo 3 – Right Wing – Courtesy of FAA



Photo 4 – Stabilator – Courtesy of FAA



Photo 5 – Aft Fuselage – Courtesy of FAA



Photo 6 – Propeller – Courtesy of FAA



Photo 7 – Nose Landing Gear – Courtesy of FAA



Photo 8 – Nose Wheel – Courtesy of FAA



Photo 9 – Stabilator Damage



Photo 10 – Wrinkle Above Firewall



Photo 11 – Firewall Damage



Photo 12 – Fuel Selector



Photo 13 – Right Fuel Tank (Viewed Through Filler Neck)



Photo 14 – Left Fuel Tank (Viewed Through Filler Neck)