



**Photo 1 – Aircraft in Water and End of Runway 5 (FAA Photo)**



**Photo 2 – Main Tire Skid Marks Leading to Aircraft (FAA Photo)**



**Photo 3 – Main Wreckage, Partially Submerged in Salt Water (FAA Photo)**



**Photo 4 – Forward Fuselage (FAA Photo)**



**Photo 5 – Right Engine and Propeller (FAA Photo)**