



Photo 1 – Front Left Quarter View of Airplane Damage. (Courtesy of FAA)



Photo 2 – Left Side of Airplane Up Against Trees. (Courtesy of FAA)



Photo 3 – Departure End of Runway 24 and Trees. (Courtesy of FAA)