



Photo 1 – Digital Photograph Provided by FAA. Left Side View of Resting Position of the Airplane on the Runway



Photo 2 - Digital Photograph Provided by FAA. View of the fractured Nose Landing Gear Fork



Photo 3 - Digital Photograph Provided by FAA. View of the Firewall