



Photo 1 – View of Wreckage as Found




Photo 2 – View of Pilot Seat



Photo 3 - View of Impact Damage to Engine Crankcase Cover



Photo 4 – Partial View of Crankshaft and Connecting Rods




Photo 5 – View of Spark Plugs after Removal



Photo 6 – View of Fuel Samples