



Photo 1 – Main Wreckage (NTSB Photo)



Photo 2 - Empennage (NTSB Photo)



Photo 3 – Right Wing (NTSB Photo)



Photo 4 – Empennage (NTSB Photo)



Photo 5 – Empennage (NTSB Photo)



Photo 6 – Engine (NTSB Photo)



Photo 7 – Engine and Fuselage (NTSB Photo)



Photo 8 – Propeller Hub, Radiator, and Engine (NTSB Photo)



Photo 9 – Fuel Tank (NTSB Photo)



Photo 10 – Propeller Tip (NTSB Photo)



Photo 11 – Fuel Valve (NTSB Photo)



Photo 12 – Spark Plugs (NTSB Photo)



Photo 13 – Propeller Blade Components (NTSB Photo)



Photo 14 – Propeller Tip (NTSB Photo)



Photo 15 – Witness Photo of Aircraft in Flight