



Figure 1 View of the wreckage inverted in the river underneath the power lines from the west bank of the Suwannee River looking east.



Figure 2 View from the river of the airplane inverted in the river under the power lines.



Figure 3 View of the right side of the airplane inverted in the river.



Figure 4 View of the left side of the airplane inverted in the river.




Figure 5 Striations on the power lines directly above the aircraft wreckage. (Photo courtesy of the FAA)



Figure 6 The airplane inverted and partially submerged on the bank of the river.




Figure 7 The airplane upright being pulled out of the river. (Photo courtesy of the FAA)