



Photo 1 – Main Wreckage



Photo 2 – Rear View of Main Wreckage



Photo 3 – Right Side View of Main Wreckage



Photo 4 – Front Seats



Photo 5 – Flap Handle



Photo 6 – Propeller Strike



Photo 7 – Broken Tree



Photo 8 – Propeller Strike



Photo 9 – Propeller Strike



Photo 10 – Propeller Strike



Photo 11 – Propeller Strike



Photo 12 – Throttle and Mixture Controls



Photo 13 – Lower Instrument Panel



Photo 14 – Propeller Spinner



Photo 15 – Propeller Blade



Photo 16 – Close Up of Trailing Edge of Propeller Blade



Photo 17 – The Other Propeller Blade



Photo 18 – Pitot Tube