

Factual Report – Attachment 3
Radar Figures and ERAM Screen Captures

AIR TRAFFIC CONTROL

ERA17FA136




Figure 2 - Zoomed overview of the last several minutes of the accident flight of N6563D as it encountered hazardous weather until radar contact was lost.




Figure 3 - Zoomed overview of the final segment of the accident flight track of N6563D after encountering hazardous weather until radar contact was lost. Arrows are included for visual reference only and do not indicate actual flight track



Figure 4 – ERAM screen capture taken at 1428 CDT and illustrating the weather that was being displayed to the ZTL radar controller just minutes before the accident.




Figure 5 - ERAM screen capture taken at 1430 CDT and illustrating the weather that was being displayed to the ZTL radar controller just minutes before the accident.