




Photo 1 – Looking northwest through debris field leading up to main wreckage.



Photo 2 – Looking southeast from the wreckage path at broken tree limbs.



Photo 3 –View of wreckage path from the cockpit.



Photo 4 –View of damaged instrument panel.



Photo 5 – View of fuselage and debris resting up against trees.