



Photo 1 – View of Main Wreckage as Found (CMI)



Photo 2 – View of Instrument Panel and Engine as Found (CMI)



Photo 3 – View of Engine after Recovery (CMI)



Photo 4 – View of Cut Tree Trunk along Wreckage Path (CMI)



Photo 5 – Cut Tree-Trunk Section Found Along Wreckage Path (CMI)