



Photo 1 – Main Wreckage (NTSB Photo)



Photo 2 - Main Wreckage (NTSB Photo)



Photo 3 - Main Wreckage (NTSB Photo)



Photo 4 - Main Wreckage (NTSB Photo)



Photo 5 – Forward Fuselage (NTSB Photo)



Photo 6 – Forward Fuselage (NTSB Photo)



Photo 7 – Fuel Tank Caps



Photo 8 - Engine (NTSB Photo)



Photo 9 - Engine (NTSB Photo)



Photo 10 – Left Fuel Tank Selector Handle (NTSB Photo)



Photo 11 – Right Fuel Tank Selector Handle (NTSB Photo)



Photo 12 - #1 Cylinder Spark Plug (NTSB Photo)



Photo 13 – Carburetor and Induction Air Filter (NTSB Photo)



Photo 14 – Cut Wood Found at Accident Site (NTSB Photo)