



Photo 1 – Overview of main wreckage.



Photo 2 – Right Wing



Photo 3 – Left Wing



Photo 4 – Vertical Stabilizer and Rudder



Photo 5 – Right Engine



Photo 6 – Left Engine



Photo 7 – Left Propeller Blades



Photo 8 – View of cut branch.