



Photo 1 – Right side of airplane damage and severed tail. (Courtesy of FAA)



Photo 2 – Left side of airplane damage. Note flattened out engine compartment and leading edge damage to both wings. (Courtesy of FAA)



Photo 3 – Photograph of impact ground scars. (Courtesy of FAA)



Photo 4 – Right side of airplane profile showing overall damage. (Courtesy of FAA)



Photo 5 – Cockpit interior damage. (Courtesy of FAA)