



Photo 1 – Side view of cargo door showing damage to rear frame



Photo 2 - Forward view of cargo door showing damage to rear frame



Photo 3- View of buckled fuselage and rear frame