



Photo 1 – Main Wreckage – Courtesy of FAA



Photo 2 – View of Left Front – Courtesy of FAA



Photo 3 – Nose Section – Courtesy of FAA



Photo 4 – Front View – Courtesy of FAA



Photo 5 – Propeller – Courtesy of FAA



Photo 6 – Skid Marks – Courtesy of FAA




Photo 7 – Close Up of Skid Marks – Courtesy of FAA



Photo 8 – Nose Landing Gear – Courtesy of FAA



Photo 9 – Forward Belly – Courtesy of FAA



Photo 10 – Top View of Vernatherm – Courtesy of FAA




Photo 11 – Side View of Vernatherm