



Photo 1 – Main Wreckage, During Recovery (Owner's Photo)



Photo 2 – Main Wreckage, View of Upper Fuselage (Owner's Photo)



Photo 3 – Main Wreckage, View of Right Side (Owner's Photo)



Photo 4 – Main Wreckage, View from Aft (Owner's Photo)



Photo 5 – Main Wreckage, Underside of Fuselage (Owner's Photo)



Photo 6 – Cockpit (Owner's Photo)