



Photo 1 – Front Right Quartering View of Entire Wreckage



Photo 2 –Wreckage Looking Down Right Wing towards Fuselage



Photo 3 – Right Wing Leading Edge Tree Impact Damage



Photo 4 – Cockpit Damage