



Photo 1 – main wreckage (FAA)



Photo 2 – Fractured Crankshaft (FAA)



Photo 3 – Front view, missing propeller (FAA)