



Photo 1 – Main Wreckage (PBI Operations Photo)



Photo 2 – Main Wreckage (PBI Operations Photo)



Photo 3 – Lower Fuselage Damage (FAA Photo)



Photo 4 – Pressure Vessel Damage (FAA Photo)



Photo 5 – Lower Fuselage Damage (FAA Photo)



Photo 6 – Nose Gear Actuator Penetration of Upper Fuselage (FAA Photo)