



Photo 1 – View of overall wreckage of airplane showing impact and thermal damage. (Courtesy of FAA)



Photo 2 – View of right side of airplane through trees looking forward. (Courtesy of FAA)



Photo 3 – View of separated wing located up in the trees. (Courtesy of FAA)



Photo 4 – View of ground scar and impact site. (Courtesy of FAA)



Photo 5 – View of separated propeller assembly. (Courtesy of FAA)



Photo 6 – View of left side of airplane resting in the trees. (Courtesy of FAA)