



Figure 1 Wreckage inverted on the ground in a heavily wooded area (Photo courtesy of FAA)



Figure 2 Fragments of the destroyed wreckage (Photo courtesy of FAA)