




Picture 2. View of Crankshaft Gear Bolt As Found



Photo 1 – Photograph of crankshaft gear bolt as found and post removal. Note damaged threads.