



Photo 1 – Right side view of helicopter damage. Note damage to building. (Courtesy of FAA)



Photo 2 – Left side view of helicopter damage and pavement ground scars. (Courtesy of FAA)



Photo 3 – View of separated tail boom. (Courtesy of FAA)