



Photo 1 – Main Wreckage (Photo Courtesy of FAA)



Photo 2 – Left Wing Damage (Photo Courtesy of FAA)



Photo 3 – Left Spar Damage (Photo Courtesy of FAA)



Photo 4 – Left Main Landing Gear Downlock Link (Photo Courtesy of FAA)