



Photo 1 – Main Wreckage (Photo Courtesy of FAA)



Photo 2 – Engine Deck (Photo Courtesy of FAA)



Photo 3 – Tailrotor Driveshaft (Photo Courtesy of FAA)