



Photo 1 – Left front view of airplane showing propeller damage. (Courtesy of FAA)



Photo 2 – Right front quarter view of airplane showing propeller damage. (Courtesy of FAA)



Photo 3 – Aft view of airplane looking forward. (Courtesy of FAA)



Photo 4 – Propeller slash gouges in runway. (Courtesy of FAA)



Photo 5 – Left main landing gear and door damage. (Courtesy of FAA)



Photo 6 – Nose landing gear broken retract mechanism. (Courtesy of FAA)



Photo 7 – Right main landing gear retract mechanism break. (Courtesy of FAA)



Photo 8 – Right landing gear door damage. (Courtesy of FAA)