



Photo 1 – View of the main wreckage in a ditch



Photo 2 – View of damaged right wing spar



Photo 3 – View of damaged right aileron and wing spar