



Photo 1 – Main Wreckage – Courtesy of FAA



Photo 2 – Right Wingtip – Courtesy of FAA



Photo 3 – Underside of Right Wing Outboard Section – Courtesy of FAA



Photo 4 – Upper Right Inboard Wing Section – Courtesy of FAA



Photo 5 -Aft View of Upper Right Inboard Wing Section – Courtesy of FAA



Photo 6 – Aft View of Upper Inboard Right Wing Section Forward of Wing Flap – Courtesy of FAA



Photo 7 – Nose Section – Courtesy of FAA



Photo 8 – Propeller Blade – Courtesy of FAA



Photo 9 – Side View of Propeller Blade – Courtesy of FAA



Photo 10 – Tree – Courtesy of FAA



Photo 11 – Close Up of Tree – Courtesy of FAA



Photo 12 – Left Wing – Courtesy of FAA



Photo 13 – Left Wing – Courtesy of FAA