



Photo 1 – Main Wreckage (Photo Courtesy of FAA)



Photo 2 – Main Wreckage Recovered (Photo Courtesy of FAA)



Photo 3 – Engine And Propeller (Photo Courtesy of FAA)



Photo 4 – Engine Exam (Photo Courtesy of FAA)