



Photo 1 – Main Wreckage (Owner’s Photo)



Photo 2 – Main Wreckage (Owner's Photo)



Photo 3 – Main Wreckage (Owner's Photo)



Photo 4 – Main Wreckage (Owner's Photo)



Photo 5 – Fuel Tank Damage (NTSB Photo)



Photo 6 – Main Rotor Hub and Mast (NTSB Photo)



Photo 7 – Main Rotor Blade (NTSB Photo)



Photo 8 – Tail Rotor Blade (NTSB Photo)