



Figure 1 Front view of the airplane in the grass (Phot courtesy of the FAA)



Figure 2 Damage to the right wing (Phot courtesy of the FAA)



Figure 3 Fractured lower nose gear bearing (Photo courtesy of the FAA)