



Photo 1 – Right Side View of Main Wreckage (Photo Courtesy of FAA)



Photo 2 – Left Side View of Main Wreckage (Photo Courtesy of FAA)



Photo 3 – Engine And Propeller (Photo Courtesy of FAA)



Photo 4 – Ignition Key (Photo Courtesy of FAA)



Photo 5 – Propeller Blade (Photo Courtesy of FAA)




Photo 6 – Engine at Examination (Photo Courtesy of Lycoming)