



Photo 2– Close up view of throttle linkage with restricted movement and resting on exhaust shroud (courtesy of FAA)



Photo 3– View of fuselage off the end of runway with wings separated (courtesy of FAA)