



Photo 1 – FAA Digital Photograph. View of the Airplane at the Accident Site



Photo 2 – FAA Digital Photograph. View Depicting the Damage to the Left Wing




Photo 3 – FAA Digital Photograph with Captions Added by NTSB. View Depicting the Connected Throttle Control and Separated Mixture Control at the Carburetor