



Photo 1 – Main Fuselage



Photo 2 – engine compartment




Photo 3 – Fuel pressure gauge line, burnt



Photo 4 - #4 cylinder head cracked



Photo 5 – #4 cylinder intake and exhaust valves