



**Photo 1 –View of Airplane at rest (Courtesy of FAA)**



**Photo 2 – View of Airplane During Recovery (Courtesy of FAA)**



**Photo 3 – View of Fractured Axle (Courtesy of FAA)**