



**Photo 1 – View of airplane from the left side partially submerged in water (courtesy FAA)**



**Photo 2 – Aft view of airplane partially submerged in water (courtesy of FAA)**



**Photo 3 – View of right side of showing airframe damage and partially submerge in water (courtesy of FAA)**



**Photo 4 – View of right wing showing inboard buckling of leading edge and airframe (courtesy of FAA)**