



Photo 1 – Left Wing (Photo Courtesy of FAA)



Photo 2 – Upper Left Wing Damage (Photo Courtesy of FAA)



Photo 3 – Upper Left Wing Tear (Photo Courtesy of FAA)



Photo 4 – Lower Left Wing Damage (Photo Courtesy of FAA)



Photo 5 – Left Main Landing Gear Strut (Photo Courtesy of FAA)