



**Photo 1 – Main Wreckage (Photo Courtesy of FAA)**



**Photo 2 – Right Wing Damage (Photo Courtesy of FAA)**



**Photo 3 – Fuselage Damage (Photo Courtesy of FAA)**