




Photo 1 – View of accident site.



Photo 2- View of Engine.



Photo 3 – View of fluid in gascolator.



Photo 4 – View of fluid in carburetor with water finding paste.



Photo 5 – View of contaminated fuel extracted from fuel system.



Photo 6 – View of water on right fuel cap test.