



Photo 1 –View of Airplane at rest (Courtesy of FAA)



Photo 2 – View of fuselage damage (Courtesy of FAA)



Photo 3 – Closer view of fuselage damage (Courtesy of FAA)