



Photo 1 – Main Wreckage



Photo 2 – Left Wing



Photo 3 – Nose Section



Photo 4 - Propeller Blade “A” – Courtesy of Textron Aviation



Photo 5 - Propeller Blade “B” – Courtesy of Textron Aviation



Photo 6 – Broken Tree – Courtesy of CMI



Photo 7 – Propeller Strike – Courtesy of CMI



Photo 8 – Engine



Photo 9 – Right Wing



Photo 10 – Fuel Selector




Photo 11 – Right Fuel Tank (View Through Filler Port)




Photo 12 – Left Fuel Tank (View Through Filler Port)



Photo 13 – Top of Right Fuel Tank Inboard Transmitter



Photo 14 – Top of Left Fuel Tank Inboard Transmitter



Photo 15 – Right Fuel Tank Gauge (Power On) – Courtesy of CMI



Photo 16 – Left Fuel Tank Gauge (Power On) – Courtesy of CMI



Photo 17 – Right Fuel Tank Inboard and Outboard Transmitters (After Removal)



Photo 18 – Left Fuel Tank Inboard and Outboard Transmitters (After Removal)



Photo 19 – Fuel from Left Tank