



Photo 1 – Overview of accident site.



Photo 2 – View of Left Wing



Photo 3 – View of Right Wing



Photo 4 – View of empennage.



Photo 5 – View of Propeller.



Photo 6 – View of Engine.



Photo 7 – View of Disassembled Gyro