



Photo 1 – View of main wreckage along debris path



Photo 2 – View of fuselage and wing



Photo 3 – Forward view of main wreckage



Photo 4 – View of empennage with elevator and rudder section



Photo 5 – View of engine and propeller at accident site



Photo 6 – Forward view of engine during examination



Photo 7 – Top view of the engine during examination



Photo 8 – Bottom view of engine during examination



Photo 9 – View of accessory section of engine during examination



Photo 10 – View of propeller during examination