

Date	Recording Tach/ Hour Meter Time	Total Time In Service	Description of work performed
8/11/2016		95.0	Disassembled and cleaned complete fuel system due to contamination. Reassembled and test run - run at high power - good. No leaks noted. Shane & Morris [redacted] A/P [redacted]
10/14/2016		95.0	R&R fuel tank to repair leak and c/w 16-08-24 (gusset fuel tank mount). Install canopy latch kit (Bag 2787). Install canopy gas strut kit. All work done IAW Vans Aircraft work spec. Shane & Morris [redacted] A/P [redacted]

Date	Recording Tach/ Hour Meter Time	Total Time In Service	Description of work performed
			R&R fuel tank to repair leak at rear assembly point (assembled by previous builder. No leaks noted.
			Shayne's Morris [REDACTED] A/P [REDACTED]
			R&R fuel tank to re-seal drain fitting (previous owner's assembly)
9/21/2017			Remove old tank and replace with new Voss Aircraft assembled tank All work done IAW Voss Aircraft installation procedures.
			Shayne's Morris [REDACTED] A/P [REDACTED]