




Änderungsstand / Modification record

Lufttüchtigkeitsanweisung bzw. Änderung: Airworthiness directive or modification:	Ges. Std.: TSN:	Datum: Date:	Unterschrift & LFZ W. Nr.: Signature & Licence no.:
11/21/13 Complied with Rotax 5/B 912-064UL crank journal by inspection with Rotax tool 876260, check good  AW 			
N 262WS TSN 95.0 Performed condition inspection, plugs, oil, and filter changes PCW by owner. Fleaked fuel system due to contamination. Test run good no leaks noted. All work done IAW Rotax Maint. Manual Shane Morris  AP 			

Lufttüchtigkeitsanweisung bzw. Änderung:
Airworthiness directive or modification:

Ges. Std.:
TSN:

95.0

Datum:
Date:

Unterschrift & LFZ W. Nr.:
Signature & Licence no.:

Shayne J Morris

[REDACTED] ASP

[REDACTED]

Disassemble carbs to remove debris.
Re-assemble. Clear all fuel lines. Disassemble
prop to remove water in one blade
Test good.