



Photo 1 – Left side of fuselage



Photo 2 – Left Wing and Left Flap



Photo 3 – Right Wing



Photo 4 – Left Elevator (cut by recovery personnel)



Photo 5 – Right Elevator (cut by recovery personnel)



Photo 6 – Vertical Stabilizer and Rudder



Photo 7 – Propeller and Spinner



Photo 8 – Aft View of Engine



Photo 9 – View of debris in engine and rotational scoring on fir trees.



Photo 10 – View of rotational scoring on power turbine blades.



Photo 11 – Hobbs Meter