



Photo 1 – View of Main Wreckage as Found (FAA)



Photo 2 – View of Fuselage Bottom as Found (FAA)



Photo 3 – View of Cockpit as Found (FAA)



Photo 4 – View of Fractured Tailboom as Found (FAA)



Photo 5 – View of Blemish on Static Line (Didado)




Photo 6 – View of Partially-Wrapped Armor Rod on Static Line as Found (FAA)



Photo 7 – View of Exemplar Dolly (left) and Accident Dolly (Right) (FAA)



Photo 8 – View of Main Rotor Blades after Recovery (Boeing)



Photo 9 – View of ‘Blue’ Rotor Blade Leading Edge Damage (Boeing)



Photo 10 - View of 'Blue' Rotor Blade Leading Edge Damage (Boeing)