



Photo 1 – Airplane Wreckage at Accident Site (photo credit: Forsyth County Sheriff's Office)



Photo 2 – Right Side of Wreckage at Salvage Facility



Photo 3 – Left Side of Wreckage at Salvage Facility



Photo 4 – Front View of Wreckage at Salvage Facility



Photo 5 – Left Side View of Engine Before Cowling was Removed at Salvage Facility



Photo 6 – Left Side View of Engine with Cowling Removed (photo credit: Lycoming Engines)



Photo 7 - No. 2 Cylinder Bore